

# nRF51822

## Product Anomaly Notice v3.0

This Product Anomaly Notice contains anomalies for the following package variants and builds of the nRF51822 chip:

Package and Variant	Build code
QFAA	HA0
	Hx0*
QFAB	CB0
	Cx0*
QFAC	AA0
	Ax0*
CDAB	AA0
	Ax0*
CEAA	EA0
	Ex0*
CFAC	AA0
	Ax0*

**Table 1** Package, Variants, and Build codes covered in this document

\* The 'x' in the build code can be any digit between 0 and 9.

### Authorization for Nordic Semiconductor

Product Manager:

Thomas Embla Bonnerud


Date:

2014-10-10

Signed:



## 1. Chip Marking



## 2. Change log

Version	Date	Change
nRF51822-PAN v3.0	2014-10-10	<p>Added: No. 69. "MPU: MPU Protect All (PALL) does not protect RAM above 8 kB from debugger access."</p> <p>Added: No. 71. "MPU: The register MPU.RLENR0 will not give runtime protection of RAM locations above 8 kB."</p> <p>Updated: No. 61. "RADIO: Designs based on nRF51822 QFN packets using balun BAL-NRF01D3 are likely to fail Korean teleregulatory requirements."</p> <p>Added: No. 74. "SPIS: ORC character is not clocked out on MISO when MAXTX = 0."</p> <p>Added: No. 73. "TIMER: Use of an EVENT from any TIMER module to trigger a TASK in GPIOTE or RTC using the PPI could fail under certain conditions."</p>
nRF51822-PAN v2.3	2014-08-12	<p>Added: No. 70. "LPCOMP: READY event is given before LPCOMP is ready"</p> <p>Added: No. 68. "MPU: Emulated system OFF mode makes MPU.DISABLEINDEBUB register inaccessible"</p> <p>Added: No. 72. "RTC: Writing to RTC registers without starting the LFCLK could lead to increased current consumption"</p> <p>Added: No. 67. "SYSTEM: Emulated system OFF mode makes POWER.RESET register inaccessible"</p>

### 3. Overview

#### 3.1 New and inherited anomalies

PAN ID	Module	Description	QFAA QFAB CDAB CEAA	QFAC CFAC	New/ Inherited <sup>1</sup>
70.	LPCOMP	READY event is sent before LPCOMP is ready.	X	X	Inherited
71.	MPU	The register MPU.RLENR0 will not give runtime protection of RAM locations above 8 kB.	X		New
69.	MPU	MPU Protect All (PALL) does not protect RAM above 8 kB from debugger access.	X		New
61.	RADIO	Designs based on nRF51822 QFN packets using balun BAL-NRF01D3 are likely to fail Korean teleregulatory requirements.	X	X	Inherited
72.	RTC	Writing to RTC registers without starting the LFCLK could lead to increased current consumption.	X	X	Inherited
74.	SPIS	ORC character is not clocked out on MISO when MAXTX = 0.	X	X	New and inherited
67.	SYSTEM	Emulated system OFF mode makes POWER.RESET register inaccessible.	X	X	Inherited
73.	TIMER	Use of an EVENT from any TIMER module to trigger a TASK in GPIOTE or RTC using the PPI could fail under certain conditions.	X	X	New
38.	WDT	The watchdog config option "RUN while paused by the debugger" does not work.	X	X	Inherited

<sup>1</sup> 'New' is anomalies introduced in the current chip version listed in Table 1, while 'Inherited' is anomalies already present in the previous chip version.

### 3.2 Fixed anomalies

The anomalies listed in this table are no longer present in the current chip versions listed in Table 1. For detailed description of the fixed anomalies, see nRF51822-PAN v2.3.

PAN ID	Module	Description
45.	AAR	AAR may exceed real time requirements.
63.	ADC	STOP task trough PPI is not functional.
44.	CCM	CCM may exceed real time requirements.
39.	GPIOTE	1V2 + HFCLK are requested always when the GPIOTE task is configured.
65.	HFCLK	A HFCLKSTOP task followed shortly by a HFCLKSTART task will disable HFCLK for up to 5 clock cycles.
59.	MPU	Reset value of the DISABLEINDEBUG register is incorrect.
60.	MPU	Device may become unrecoverable when the MPU function NVM protect blocks is used in combination with UICR Protect all.
68.	MPU	Emulated system OFF mode makes MPU.DISABLEINDEBUG register inaccessible.
41.	POWER	RESETRAS register may erroneously indicate LOCKUP.
57.	PPI	Concurrent operations on the PPI peripheral will fail.
42.	SYSTEM	Writing to RAM right after reset or turning it ON fails.
43.	TEMP	Using PPI between DATARDY event and START task is not functional.
62.	TIMER	Accessing the TIMER's SHUTDOWN task through PPI does not give the expected result.
35.	TWI	Consumes too much current when it is enabled and the STOP task is triggered.
56.	TWI	TWI module lock-up.
40.	UART	CONFIG register read value is wrong.
58.	UART	RTS line indicates ready to receive data for one clock cycle when the UART reception is off.
48.	WDT	Reset value of the CRV register is incorrect.

#### 4. New and inherited anomalies

<p><b>70. LPCOMP: READY event is sent before LPCOMP is ready.</b></p>
<p><b>Symptoms:</b></p> <p>May receive unexpected events and wakeups from LPCOMP.</p>
<p><b>Conditions:</b></p> <p>LPCOMP is configured to send an event or to wake up the chip. LPCOMP.TASKS_START task is set and LPCOMP.EVENTS_READY event has been received.</p>
<p><b>Consequences:</b></p> <p>Unpredictable system behavior caused by false triggered events and wakeups.</p>
<p><b>Workaround:</b></p> <p>Use the following configuration sequence:</p> <ol style="list-style-type: none"> <li>1. Configure the LPCOMP to send an event or wake up the chip, but do not enable any PPI channels or IRQ to be triggered from the LPCOMP events.</li> <li>2. Trigger the LPCOMP.TASKS_START task and wait for the LPCOMP.EVENTS_READY event.</li> <li>3. After receiving the LPCOMP.EVENTS_READY event wait for 36 <math>\mu</math>s.</li> <li>4. After 36 <math>\mu</math>s, clear the LPCOMP.EVENTS_DOWN, LPCOMP.EVENTS_UP and LPCOMP.EVENTS_CROSS events.</li> </ol> <p>LPCOMP is now ready to be used.</p>
<p><b>71. MPU: The register MPU.RLENR0 will not give runtime protection of RAM locations above 8 kB.</b></p>
<p><b>Symptoms:</b></p> <p>Code running from region 1 accessing RAM in region 0 that is located above the first 8 kB does not give a hard fault exception as specified in the nRF51 Series Reference manual.</p>
<p><b>Conditions:</b></p> <p>Always when the RAM is divided into two regions.</p>
<p><b>Consequences:</b></p> <p>Missing runtime protection of addresses above 8 kB will make it harder to detect unintended write operations to RAM region 0 from code region 1. Such unintended write operations could lead to malfunction of the firmware.</p>
<p><b>Workaround:</b></p> <p>None. (Debugging of the code could be done using the xxAC version of nRF51822/nRF51422 where this PAN is fixed).</p>

<b>69. MPU: MPU Protect All (PALL) does not protect RAM above 8 kB from debugger access.</b>
<b>Symptoms:</b> Reading RAM using Serial Wire Debug (SWD) returns the actual RAM content, and not 0x00 as specified in the nRF51 Series Reference manual.
<b>Conditions:</b> Always when UICR.RBPCONF.PALL is set to 0x00.
<b>Consequences:</b> RAM addresses above 8 kB will be accessible using the SWD interface.
<b>Workaround:</b> None.

<b>61. RADIO: Designs based on nRF51822 QFN packets using balun BAL-NRF01D3 are likely to fail Korean teleregulatory requirements.</b>
<b>Symptoms:</b> LO leakage is too high.
<b>Conditions:</b> Designs based on the QFN packets nRF51822-QFAA/nRF51822-QFAB combined with ST Microelectronics balun, BAL-NRF01D3 (as described in the reference layout nRF51822-DF-ST v1.0).
<b>Consequences:</b> The designs are likely to fail Korean teleregulatory spurious emission limits due to LO leakage.
<b>Workaround:</b> There are several alternative baluns to BAL-NRF01D3, please refer to <a href="http://www.nordicsemi.com">www.nordicsemi.com</a> for details.

<b>72. RTC: Writing to RTC registers without starting the LFCLK could lead to increased current consumption.</b>
<b>Symptoms:</b> Increased current consumption.
<b>Conditions:</b> Setting up the RTC by writing to its registers without starting the LFCLK.
<b>Consequences:</b> The user will experience an increase in the current consumption of ~1 mA.
<b>Workaround:</b> Always run the LFCLK for a minimum of one LFCLK clock cycle after writing to the RTC registers.

<b>74. SPIS: ORC character is not clocked out on MISO when MAXTX = 0.</b>
<b>Symptoms:</b> The SPIS does not send the ORC character as expected.
<b>Conditions:</b> SPIS is configured with MAXTX = 0.
<b>Consequences:</b> Data sent on the MISO line is not the ORC character but the data pointed to by the TXDPTR.
<b>Workaround:</b> In the case where the SPI slave does not have any data to be sent (MAXTX = 0). Set MAXTX = 1, with the first byte in the TX buffer set equal to the ORC character.

**67. System: Emulated system OFF mode makes POWER.RESET register inaccessible.****Symptoms:**

Pin reset using the debugger does not work.

**Conditions:**

Device is in emulated System OFF mode.

**Consequences:**

Pin reset using the debugger does not work.

**Workaround:**

Before pin reset, halt the core and generate a soft reset. This will take the device out of Emulated System Off, making the POWER.RESET register accessible.

**Note:** Latest Nordic Semiconductor tools already perform this action automatically.

**73. TIMER: Use of an EVENT from any TIMER module to trigger a TASK in GPIOTE or RTC using the PPI could fail under certain conditions.****Symptoms:**

One or more EVENTS from the TIMER module are lost.

**Conditions:**

Routing TASK's from the TIMERx module to GPIOTE or RTCx using the PPI and at the same time going into sleep mode.

**Consequences:**

One or more TASKS triggering are lost.

**Workaround:**

Use the following code when using any Timer in those conditions:

```
*(uint32_t *)0x40008C0C = 1; //for Timer 0
*(uint32_t *)0x40009C0C = 1; //for Timer 1
*(uint32_t *)0x4000AC0C = 1; //for Timer 2
```

When the conditions are no longer met, use the following code:

```
*(uint32_t *)0x40008C0C = 0; //for Timer 0
*(uint32_t *)0x40009C0C = 0; //for Timer 1
*(uint32_t *)0x4000AC0C = 0; //for Timer 2
```

A typical code workaround for an application that use TIMER2 to route TASKS to a GPIOTE can be:

```
/* Add workaround when starting timer2 */
*(uint32_t *)0x4000AC0C = 1; //for Timer 2
NRF_TIMER2->TASKS_START = 1;

/* Add workaround when stopping timer2 */
NRF_TIMER2->TASKS_STOP = 1;
*(uint32_t *)0x4000AC0C = 0; //for Timer 2
```

**38. WDT: The watchdog config option "RUN while paused by the debugger" does not work.****Symptoms:**

The debugger and micro-controller do not communicate. The micro-controller does not run any code.

**Conditions:**

The watchdog is configured to "run while halted by the debugger", and the watchdog timer expires with the debugger connected.

**Consequences:**

The debugger and micro-controller do not communicate. The micro-controller does not run any code.

**Workaround:**

Do not configure the watchdog timer to run while paused by the debugger.